Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
52	1	"20010009219"	US-PGPUB; USPAT	OR	ON	2005/01/25 18:57
S3	137	Tanaka-Yoshiyuki	US-PGPUB; USPAT	OR	ON	2005/06/14 21:36
54	1	Tanaka-Yoshiyuki and cancel\$3 near cam	US-PGPUB; USPAT	OR	ON	2005/01/25 18:58
S5	36	Tanaka-Yoshiyuki and switch	US-PGPUB; USPAT	OR	ON	2005/06/14 21:35
S6	. 4	Tanaka-Yoshiyuki and switch and steering	US-PGPUB; USPAT	OR	ON	2005/01/25 18:58
S7	16	Tanaka-Yoshiyuki and cable	US-PGPUB; USPAT	OR	ON	2005/01/25 19:01
S8	189	spiral cable	US-PGPUB; USPAT	ADJ	ON	2005/01/25 22:17
S11	2	spiral cable with cam	US-PGPUB; USPAT	ADJ	ON	2005/06/14 21:42
S20	50	("6472412" "6303600" "6255326" "6280918" "3638882" "4630997" "6261750" "5745599" "4345051" "5699305" "6476610" "3697564" "5848201" "5872872" "6280920" "6351569" "5338725" "3879440" "5263815" "5386973" "6344863" "6720837" "6606569" "6236754" "6463569" "6465518" "5583528" "5828354" "5841412" "6373408" "5202307" "6186170" "4455519" "5835973" "6468729" "5758774" "6376674" "5910216" "6337176" "3904835" "4906909" "5311177" "5557273" "5598453" "6549665" "6756921" "6413980" "6342503" "5614471" "4026946").pn.	USPAT	OR	ON	2005/06/14 21:43
S21	50	("4065260" "6291730" "6281307" "6358979" "6251902" "6429313" "6432945" "5649246" "5335097" "4602893" "4618285" "6154157" "6169503" "6310191" "6303593" "6433171" "6323295" "4254345" "6313140" "6380691" "6464777" "6278000" "6306875" "6258957" "6462063" "6274301" "4298751" "6137732" "6303683" "6372764" "5182748" "6673330" "6727347" "6172681" "6337317" "5552418" "5591775" "6455587" "6440957" "6420403" "6580287" "6714151" "6262241" "5683281" "5800924" "5858486" "6365356" "6433458" "4632254" "5225793").pn.	USPAT	OR	ON	2005/06/14 21:42

			,	<del>,</del>		
S22	189	spiral cable	US-PGPUB; USPAT	ADJ	ON	2005/06/14 21:41
S23	137	Tanaka-Yoshiyuki	US-PGPUB; USPAT	OR	ON	2005/01/25 22:17
S24	1	S22 and S23	US-PGPUB; USPAT	OR	ON	2005/01/25 22:18
S25	2973	200/61.27-61.38,61.54,302.1-302.3. ccls.	USPAT	OR	ON	2005/06/14 21:45
S26	937	439/11,13,15,164.ccls.	USPAT	OR	ON	2005/06/14 21:47
S27	30	spiral cable and cam	US-PGPUB; USPAT	ADJ	ON	2005/01/25 22:21
S28	6	spiral cable same cam	US-PGPUB; USPAT	ADJ	ON	2005/01/25 22:22
S29	. 2	spiral cable with cam	US-PGPUB; USPAT	ADJ	ON	2005/01/25 22:23
S30	40	200/61.27-61.38,61.54,302.1-302.3. ccls. and spiral	USPAT	OR	ON	2005/01/25 22:25
S31	119	439/11,13,15,164.ccls. and spiral	USPAT	OR	ON	2005/01/25 22:24
S32	18	439/11,13,15,164.ccls. and spiral near (cable or connector)	USPAT	OR	ON	2005/01/25 22:29
S33	2	439/11,13,15,164.ccls. and spiral near (cable or connector) same cam	USPAT	OR	ON	2005/06/14 21:48
S34	6	200/61.27-61.38,61.54,302.1-302.3. ccls. and spiral near (connector or cable)	USPAT	OR	ON	2005/01/25 22:27
S35	1	200/61.27-61.38,61.54,302.1-302.3. ccls. and spiral near (connector or cable) and cam	USPAT	OR	ON	2005/01/25 22:26
S36	50	("6022230" "6271515" "6299453" "4292759" "4346893" "4556397" "5943735" "5269389" "4608478" "4340189" "4981378" "4462779" "4820363" "4953808" "5068501" "5328120" "5333811" "5607116" "5775614" "6198595" "4896373" "5766065" "5928066" "5709520" "3791293" "4372452" "4386744" "4553714" "4884785" "6364079" "4881020" "6196348" "4354637" "4438551" "4583762" "4866917" "5553445" "6052973" "4346842" "4379566" "4416469" "4434864" "4515362" "4768809" "4772046" "4819758" "4823576" "4849037" "4860454" "4974876").pn.	USPAT	OR	ON	2005/01/26 15:41

S37	38	("4354339" "5337694" "5573078" "6241453" "6704829" "5727981" "4844359" "4928901" "4936782" "4975064" "5248260" "5393007" "5692915" "5816733" "5890921" "5913488" "5944544" "5975453" "5993228" "6019621" "6065707" "6152394" "6196488" "6228425" "6305958" "6332793" "6457549" "6475007" "6494396" "6500016" "6514100" "6547606" "6572393" "6767216" "4855543" "5242309" "5781978" "5847342").pn.	USPAT	OR	ON	2005/01/26 15:42
S38	27	steering wheel and spiral cable	USPAT	ADJ	ON	2005/01/26 19:08
S39	9	"5773776"	USPAT	OR	ON	2005/01/26 20:46
S41	7	MATSUMOTO-TSUYOSHI and switch and lever and connector	USPAT	OR	ON	2005/01/26 20:47
S42	2546	200/61.27-61.38,61.54.ccls. or 439/11,13,15,164.ccls.	USPAT	OR	ON	2005/01/26 20:59
S43	1319	200/302.1-302.3.ccls.	USPAT	OR	ON	2005/01/26 20:59
S44	4	S42 and S43	USPAT	OR	ON	2005/01/26 21:44
S62	2566	200/61.27-61.38,61.54.ccls. or 439/11,13,15,164.ccls.	USPAT	OR	ON	2005/06/14 21:32
S64	36	Tanaka-Yoshiyuki and switch	US-PGPUB; USPAT	OR	ON	2005/06/14 21:35
S65	144	Tanaka-Yoshiyuki	US-PGPUB; USPAT	OR	ON	2005/06/14 21:37
S66	8	Tanaka-Yoshiyuki and "439"/\$.ccls.	US-PGPUB; USPAT	OR	ON	2005/06/14 21:37
S68	1	"20010009219"	US-PGPUB; USPAT	OR	ON	2005/06/14 21:40
S69	0	spiral cable and steering column assembly	US-PGPUB; USPAT	ADJ	ON	2005/06/14 21:42
S71	2	spiral cable with cam	US-PGPUB; USPAT	ADJ	ON	2005/06/14 21:50

S72	50	("4065260" "6291730" "6281307" "6358979" "6251902" "6429313" "6432945" "5649246" "5335097" "4602893" "4618285" "6154157" "6169503" "6310191" "6303593" "6433171" "6323295" "4254345" "6313140" "6380691" "6464777"	USPAT	OR	ON	2005/06/14 21:42
	·	"6278000" "6306875" "6258957" "6462063" "6274301" "4298751" "6137732" "6303683" "6372764" "5182748" "6673330" "6727347" "6172681" "6337317" "5552418" "5591775" "6455587" "6440957" "6420403" "6580287" "6714151" "6262241" "5683281" "5800924" "5858486" "6365356" "6433458" "4632254" "5225793").pn.				
S73	50	("6472412" "6303600" "6255326" "6280918" "3638882" "4630997" "6261750" "5745599" "4345051" "5699305" "6476610" "3697564" "5848201" "5872872" "6280920" "6351569" "5338725" "3879440" "5263815" "5386973" "6344863" "6720837" "6606569" "6236754" "6463569" "6465518" "5583528" "5828354" "5841412" "6373408" "5202307" "6186170" "4455519" "5835973" "6468729" "5758774" "6376674" "5910216" "6337176" "3904835" "4906909" "5311177" "5557273" "5598453" "6549665" "6756921" "6413980" "6342503" "5614471" "4026946").pn.	USPAT	OR	ON	2005/06/14 21:43
S74	2993	200/61.27-61.38,61.54,302.1-302.3. ccls.	USPAT	OR	ON	2005/06/14 21:45
S75	943	439/11,13,15,164.ccls.	USPAT	OR	ON	2005/06/14 21:47
S76	2	439/11,13,15,164.ccls. and spiral near (cable or connector) same cam	USPAT	OR	ON	2005/06/14 21:48
S77	0	spiral cable with cancel cam	US-PGPUB; USPAT	ADJ	ON	2005/06/14 21:50
S78	1	spiral cable same cancel cam	US-PGPUB; USPAT	ADJ	ON	2005/06/14 21:50